

DIRECT SERVICE UNITS

1755 HOLLAND PKWY., SOUTH

BARTOW, FLORIDA 33830

111 NORTH 11TH STREET

HAINES CITY, FLORIDA 33844

305 WEST CENTRAL AVENUE

LAKE WALES, FLORIDA 33853

103 EAST CANAL STREET

MULBERRY, FLORIDA 33860

DISTRICT EIGHT POLK COUNTY HEALTH DEPARTMENT

WILLIAM F. HILL, JR., M.D.

DIRECTOR

SE TEMP - POSE HEAVILLE

P.O. BOX 1480 229 AVENUE D, N.W. WINTER HAVEN, FLORIDA 33880

June 24, 1977

Rad Health/ Land Survey Shady Lake Estates Phase I

DIRECT SERVICE UNITS

1333 NORTH FLORIDA AVENUE LAKELAND, FLORIDA 33801

P.O. BOX 33 WAVERLY, FLORIDA 33877

2 NORTH REEDY BLVD. FROSTPROOF, FLORIDA 33843

243 E. LAKE AVENUE AUBURNDAĻE, FLORIDA 33823

Rick Strawbridge 5313 Sorrento Lakeland, Florida 33803

Dear Mr. Strawbridge:

Less than .01 mR/hr



This is to confirm your receipt of the rough gamma survey for the above referenced project. As mentioned in our last meeting the survey values are above those levels that are recommended for residential construction by United States Environmental Protection Agency. Their guideline is as follows:

> Interim Recommendations For Gamma Exposure Levels At New Structures Sites on Florida Phosphate Lands

External Gamma Radiation Level

Equal or greater than 0.01 mR/hr

Recommendations

Construction should be delayed pending additional study or acceptable control technology should be instituted to preclude indoor radon daughter problems

Construction may be ini-

As previously discussed with you since this land was filled with material from the adjacent phosphate pits, this agency feels that the fill material which is to be located under each structure should be removed and replaced with satisfactory soils. This process would minimize the possibility of elevated radon daughter products in the structures upon their completion. We will be glad to consult with you and your clients on this matter should you have any questions.

Sincerely.

Donald R. Guthrie, P.E.

Sanitary Engineer

DRG: mnk

SITE: Florida Phosphate
BREAK: 17.8
OTHER: V. 31

31,1

LINRECORDED

SHADY

LAKE

ESTATES

PHASE I DESCRIPTION

THE INEST 300.0 FEET OF THE EAST 1/2 OF THE SOUTHWEST 1/4 OF SECTION 12, TOWNSHIP 29 SOUTH, RANGE 23 EAST, LESS THE SOUTH 1416.0 FEET THEREOF. South FAST CORNER OF INTERSECTION OF PORKIN Rd and DORMAN Rd, LAKELAND

613.0

,

All gamma Radiation Values ARIN MR/AR AS Ludlum 125 # 3644


10 10	10 10	9 19 11	17 4 - 16 1 TRACT A 1-0
12	103	10 2 16 10 22 20 30	18
76	16 16 185 HOLE #2	17 20 % 16 14 18	20 10 1131 Hart 1
18 10 10 6 2	10 2 10	6 100 6	14

LINRELORDED

SHADY LAKE EG

PHASE I DESCRIPTION

THE WEST 300.0 FEET OF THE EAST 1/2 OF THE SOUTH WEST 1/4 OF SECTION 12, TOWNSHIP 29 SOUTH, RANGE 23 EAST, LESS THE SOUTH 1416.0 FEET THEREOF.



DORMAN

LINRECORDED

SHADY LAKE ESTATES

•	PHANE I DENCE	21PTION	
THE WEST 3		EAST 1/2 OF THE 3 EAST, LESS THE	SOUTH HALD FEE
THEREOF.			•
122.37	11.31	100	11
12	11	10	9
	A	s # 8 ro #12 11 Readings	=
	TEST Haetb	370 10 MR/hR	TEK HOLE
122.31	91.51	100	11